

to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME *S.S. "Virginia Dollar"* Report *N.Y.K.* No. *23956*

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/6/02.)

Nature of Survey \_\_\_\_\_

*Damage.*

When due \_\_\_\_\_

*no 5.5. 11:2 due 7.23.*

*Vessel to be placed in dry dock for examination, and  
permanent repairs on arrival in New York.  
For repairs required see reports.*



© 2021

Lloyd's Register  
Foundation

608158-008167-0263