

nt to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

SS Wayfarer

Report

No.

8805

For the ~~CHIEF SHIP SURVEYOR~~ and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ature of Survey

MB safety valves When due

This vessel's machinery & boilers were classed with Record
 - LMC 2,03 subject to the main boiler safety
 valves being satisfactorily altered on her return

A Ltr. has now been received from the L.S.
 Surveyors in which they state that arrangements
 have now been made to have the matter attended to
 on the vessel's next return in about five weeks
 time.

The above proposal is submitted for approval.

[Signature]
 6.5.03

[Signature]
 6.5.03

L.S. 8/5/03



© 2021

Lloyd's Register
Foundation

008158-008167-0270

S, In 'tween Deck, size and spacing

Hold

Quarter 'tween Dks

2 1/8	3	2 1/4	2 1/8	2 1/4
4 3/4	5 1/4	4 3/4	5 1/4	

"

The Plates

Deck. Material and thickness