

4 E

ived by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

"TAIZIN MARU"

Rpt.

Smk.

No. 2583

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

ure of Survey

REPAIRS ~~TO ENGINES AND BOILERS~~ DUE TO DAMAGE THROUGH GROUNDING.

Repairs effected to dynamo engine and some pumps, and minor repairs.

It is submitted the vessel is eligible to remain as classed without fresh record of survey.

A limit to examine the starboard screw shaft expires 5.41.

008168-008176-0157

8.8.40.

© 2020
Lloyd's Register
Foundation