

" TANGARA "

In view of the age of this ship it is considered that a much more extensive examination than the preliminary inspection which the Owner proposes would be necessary to enable him to reach a decision regarding repair.

It is, therefore, submitted that Mr. Rolland be informed that on receipt of a request signed by the Owner the Committee would instruct the Rio de Janeiro Surveyor to carry out a special survey for reclassification of the hull of this ship. The Owner could then base his decision upon the repairs recommended by the Surveyor.

The United Kingdom fee for survey D (based on equipment numeral w) is £62.0s.0d.

*[Handwritten signature]*

20th September, 1951.



© 2021

Lloyd's Register

008186-008200-0278