

DISCLOSED

SECTION

No. 586

(Received at London Office)

Lon. No. 128999

# REPORT OF SURVEY FOR REPAIRS, &c.

Writing Report 19... When handed in at Local Office 19... Port of...  
No. in Reg. Book 60217 Survey held at on the Wood, Iron or Steel Tw. Sc M.V. FLORITA Date, First Survey Last Survey 19...  
(No. of Visits)

TONNAGE: — Built at TONNING By whom Schiffman & Mel. Mania When 1920  
GROSS 623 Owners Hermamos Ayo Owners' Address  
UNDER DEK 542 Managers Port belonging to Puerto Cortes Honduras  
NET 348

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage  
Cell DB or DBa feet: uE&B feet: f feet  
total capacity tons. FPT tons: APT tons: MT feet tons.  
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Only alterations in the existing records of tanks should be inserted.  
N.B.—All alterations in the existing records should be underlined.

Last Report, No. 1755. Port Gek.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Was a damage report made by anyone else? if so, by whom?

Al. with Freeboard LMC CS 11.51  
corresponding to an + NDB 4.46  
extreme Summer DBS 11.52  
draught of 14' 4" TS P 11.52  
2.54 TS 09.5 (N) 2.54  
SS. GAL - 4.46 (DA) NEMADE 44 FITE 46  
SS. HNA - 9.50 MEXICO, CARIBBEAN SEA PANAMA  
Society's Freeboard (if assigned) as PACIFIC COASTS OF T.C.  
painted on Ship and now verified OIL ENGINES COLONIA PANAMA  
CONTINUOUS SURVEY.

REPAIRS, OR EXAMINATION AS PER RULE FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors.	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed, ...								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE			
Decks	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
Caulking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month Year
Coamings	Cement or Asphalt	Oil Bunkers	Boats
Beams & Fastenings	Rudder	Scuppers	Masts, Yards, &c.
Outside Plating	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed.)
" " in way of sidelights	Windlass	Hatches	Equipment letter
Frames	Have pumps been examined and found efficient?	Planking	Anchors, No. of
Reverse Frames	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
Longitudinals	Have Watertight Doors been examined and found efficient?	Treenails	" length mean diamr. (on board.)
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	" Rule length size
Floors	Air and Sounding Pipes	Transoms, Pointers & Crutches	Chain Locker
Keelsons	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Hawsers & Warps
Stringers		" " at other places	Standing and Running Rigging
Inner Bottom Plating		Stringers, Clamps & Shelves	Sails
Have the Tanks been examined internally?		Salting	
Have the Tanks been tested?		State if examined	

## General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 23)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 23)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute

Character Assigned

FRIDAY - 5 NOV 1954

GENERAL COMMITTEE

Thursday

25th November, 1954

Classing Committee's decision confirmed.

Surveyor to Lloyd's Register of Shipping.

2021

Lloyd's Register Foundation

008217 - 008221 - 00837