

1

Sent to Chief Surveyors.....

GB

SHIP'S NAME

"ENR ICHETTO"

Received from Chief Surveyors.....

REPORT

N. Ns.

No. 6955

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.).

Nature of Survey.....

DOCKING: H.W. DAMAGE.

~~When X~~

Subject to sternframe solepiece (E.W. & reinforced 4,53) and indented shell plates G.2 & I.13 (s.s.) being specially examined at next drydocking, to D.B. tank top plating (p.s.) in No.5 hold being examined and dealt with as necessary at the Special Survey, and to No.1 D.B. tank being examined and dealt with as necessary on arrival at Genoa.

2,55 N.Ns. Subject.

*J.H.*  
22.3.55



© 2020

Lloyd's Register  
Foundation

008231-008236-0052