

008231-008236-0151

Surveyors _____

Received from Chief Surveyors _____

NAME Stl & M/V "L. T. C. No 1"Report Bos No. 2538**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Survey _____

1st Entry

When due _____

➤ A.1. (Steel) oil Barge. Carrying ^{state} Petroleum in Bulk
 "In Service on New York Barge Canal and from New York
 "to Belfast, he via Long Island Sound and Cape Cod Canal
 1 D¹¹ (Stl) • Web Frames, Longitudinal framing, Bracketless system.
 F.P.T. 1250, A.P.T. H15.
 F.K. 7 B.H, pt asp, Lloyd's A.C.P.
 Q 17[?], Bridge over machinery space 35'
 machy aft



© 2020

Lloyd's Register
Foundation

is concluded the diameter of the steering chain. to go required but
 the surveyor should be requested to state if this is so.