

2014/34

The class is subject to the intermediate stop valve chest on the centre boiler being renewed at the Owners convenience.

5E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME "COLONEL VIELJEUX"

Rpt.

Msl. No. 10494

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

~~DAMAGE & WEAR AND TEAR.~~


Intermediate stop valve chest on the centre boiler now renewed.

The superheater elements were found to be considerably wasted but no repairs could be carried out at this time. The superheaters have been accordingly put out of use and the steam pipe arrangements modified as a temporary measure. The main feed check valve chest renewed.

It is submitted the vessel is eligible to remain as classed with

~~record of Survey as recommended.~~

Without special conditions.



© 2021

Lloyd's Register
Foundation

6. 3. 47.

008237. 008247. 0093

pipes leading to the main engine. New piping were tested to rule requirements