

15 MAR 1949

Received from Chief Surveyors.....

t to Chief Surveyors.....

GB

VESSEL'S NAME

"LADY STANLEY"

REPORT

Lon.

No. 117329A

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey.....

When due.....

The class is subject to permanent repairs to indented shell plates B.8 & 9 and C.10 (s.s.) and to cant plating at the Owners' convenience.

A letter dated 2.3.49 has been received from the Owners, intimating that they have decided not to continue this Trawler's class.

IT IS ACCORDINGLY SUBMITTED the class of this ship be withdrawn from the Register Book, and three dots (...) inserted in lieu, indicating that the class has been withdrawn at the Owners' request.

Withdraw Class.Insert in R.B.

(...) 3.49.

14
11/3
49
[Signature]



© 2021

Lloyd's Register
Foundation

008237.008247.0300

Y.M.
on P
d, M

Es, &

how
wed
lettero. of
to ifth
(on
len

Chain Locker

Hawsers & Wa