

2m.7.44.

1

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME "LADY STANLEY" REPORT Liv. No. 123250

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey DMG. & A FURTHER 2nd S.S. No. 3 ~~when due~~ vessel 28 years old.

Subject to permanent repairs to indented shell plates

B.8 & 9 and C.10 (s.s.) at the Owners' convenience.

Vessel reconditioned for Fishing Service.

See Hul.Rpt.53140 for later docking date.

W.H.  
29.10.45



© 2021

Lloyd's Register  
Foundation

008237-008247-0308

Have the Tanks been tested? ..... Doubling Plates under Sounding Pipes.....

(State if examined.)

Sails.....