



all fees pd.

1E

Chief Engineer Surveyor _____

Received from Chief Engineer Surveyor _____

S NAME Thorhild Rpt. Got. No. 10365

marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

pe of Engine Oil Engines 4 S.C.S.A.
12 Cy. 24 ¹³/₁₆" - 47 ¹/₄" 711 NHP.

If Boilers fitted with forced draught	<i>No main boiler</i>
Tail Shaft. If fitted with a continuous liner	<i>Yes</i>
If fitted with an outside gland of approved type	<i>No</i>

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed + LMC 8.35
2 DB 150 lbs.

The Surveyors should be requested to forward certificates of test for the electric generator in accordance with Section 2, clause 1, of the Rules for Electrical Equipment; unless these generators have been constructed under special survey.

 © 2021
[Signature]
15/10/35
Lloyd's Register Foundation

