

ed by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

SEL'S NAME

Richmond Hill

Rpt.

Rec. No. 98976
Sld. No. 33009
Arch. " 100513

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/24)

Type of Engine

Triple Expansion.

If Boilers fitted with forced draught

Tail Shaft. If fitted with a continuous liner

If fitted with an outside gland of }
approved type

Yes
Yes
Yes
No

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

*+ LMC 11.40.**Fitted for oil fuel 11.40, F.P. above 150°F.**2 SB. (Ch.) } F.D.**1 Aux. SB }**Rht.**L.F.*
6/12/40.

© 2020

Lloyd's Register
Foundation

008279 - 008287 - 0090