

1

Stanland

DISCLOSED
SECTION. 536

Sent to Chief Surveyors 1/1/12

Received from Chief Surveyors

VESSEL'S NAME

At St Bordenland

Report

Sto

No. 32197

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24.6.92)

Nature of Survey

First entry

When due

± 100A-1. (2lab)
2 Dr (2d)

17 B. bul DBa 58 n 322 f 116 257E FRT 481 APT 256
FK + BK 15" ABH Cum Lloyd ARGP 373 F33

M

22/3/11
1/1/13



© 2021

Lloyd's Register
Foundation

008288-008295-0105

BEAMS, Third and Fourth Deck, Single Angle, }
Bulb Angle, Plate, Tee Bulb, or Channel }

Angle on ditto

Tie Plates