

2. Grip. of riveting: cir. seams *DR L* long. seams *J.R. D.B.S.* Diameter of rivet holes in long. seams

SS. P.L.M 12.

his vessel was built at West Hartlepool 12.20.  
Sustained damage due to grounding on  
the 14th Dec.

he Newcastle Surveyors report by wire  
that the necessary repairs have been  
ompleted

It is submitted that  
this vessel is eligible for  
**THE RECORD.** + L.M.C. 12.20 F.D

R.M.

25/1/21

© 2020

Lloyd's Register  
Foundation

008296-008304-0141

OPTICAL DONKEY BOILER—

No.

Description

Manufacturers of