

DISCLOSED

REPORT OF SURVEY FOR REPAIRS, &c.

SECTION

No. 619

No. of writing Report 19... When handed in No. Local Office 19... Port of...
No. in Reg. Book Survey held at... Date, First Survey... Last Survey 19...66406 on the Wood, Iron or Steel Range KOBODAK.
TONNAGE:— Built at Wellington Quayen Tyne By whom Islelands (Successors) When YEAR 1950 MONTH 11
GROSS 564 Owners India Gen Nav. Rly. Co. Ltd Owners' Address...
UNDER DK. 546 Managers...
NET 564 Managers...
(If not already recorded in Appendix to Register Book)
Port belonging to London.Surveyed Afloat or in Dry Dock? Name of Dock... Destined Voyage...
Cell DBor DBa... feet; uE&B... feet; f... feet
total capacity... tons: FPT... tons; APT... tons; MT... feet... tons.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

1st Report, No. 16117. Port Cal.

Medical Surveys, when held, must be reported in detail and pariatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the placement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form also the dates and initials of any letters respecting this case.

In cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE FOR

DESCRIPTION OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors.	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed, ...								
Removed and Faired or Repaired								
Red or Repaired in place ...								

CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M.
of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	(State if on Felt.)
Fastenings	Cement or Asphalt	Oil Bunkers	When fitted, Month Year
Plating	Rudder	Scuppers	Boats
in way of sidelights	Steering gear and its connections	Cargo Hatchways	Masts, Yards, &c.
Frames	Windlass	Hatches	Condition, how ascertained
Planks	Have pumps been examined and found efficient?	Planking	(State if wedges removed.)
Planks	Have Sluice Valves been examined and found efficient?	Caulking	Equipment letter
Planks	Have Watertight Doors been examined and found efficient?	Treenails	Anchors, No. of
Planks	Have Ventilators and their Coverings been examined and found efficient?	Breasthooks & Stemson	Cables (State if now ranged)
Planks	Air and Sounding Pipes	Transoms, Pointers & Crutches	length mean diamr
Planks	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	(on board.)
		Stringers, Clamps & Shelves	Rule length size
		Salting	Chain Locker
		State if examined	Hawsers & Warps
			Standing and Running Rigging
			Sails

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 23)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 23)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19

FRIDAY 30 JUL 1954

Committee's Minute

Character Assigned

Surveyor to Lloyd's Register of Shipping.

GENERAL COMMITTEE

Thursday 23rd September 1954

Classing Committee's

decision confirmed.

Lloyd's Register Foundation

008386-008392-0007