

Surveyor to assure himself of the thorough efficiency of those parts of each boiler  
State latest date of internal examination of each boiler

Present condition of funnel

4 E

13.  
by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

1949

SEL'S NAME HELLENIC CHRYSOULA.

REPORT

Nwc. No. 106401.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey REPAIRS TO ENGINES ~~AND BOILERS~~ DUE TO DAMAGE THROUGH STRIKING A BUOY.

Vessel examined on slipway.

Screw shaft drawn and examined and the spare propeller fitted.

IT IS SUBMITTED that this vessel is eligible to remain as classed with notation of S. 7,49 subject to a spare propeller being supplied at the first opportunity.

© 2021

Lloyd's Register  
Foundation

18.10.49.

008386-008342-0045