


In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his

Rpt. 7a



For the information of Surveyors and the Committee only.

Received at _____ Office, 10 OCT 1949 19__

Lloyd's Register of Shipping.

(Report on Machinery, No. 23889 Port GRIMSBY.)

No. 443

ENGINE or BOILER VALVES or CONNECTIONS.

I have to report that the Details, as herein described, manufactured by Messrs C. D. Holmes of Hull (Pat. No. 9,1670) Shire Trawlers Ltd. Grimsby, for the Engines or Boilers No. _____ being constructed by _____ of _____

have been inspected by me as set forth below, and found to be, so far as can be seen, sound and free from defects.

These have been despatched to Grimsby

Stamp Mark.

LLOYD'S TEST
550 lbs.
No. MC 21-9-48.

M. Chambers
25-9-48.

and description.	2 - 1 1/4" G.M. Right Angle Valves.
Stress Test: per square inch.	550
Defects, if any.	-
When Inspected.	21-9-48.



© 2020

Lloyd's Register Foundation

MADE AND PRINTED IN ENGLAND)

Fee 10/6.

008393-008400-0071

(per Section 29.)
Shipping expenses (if chargeable) £ : : Received by me, 19__

Engineer Surveyor

1906/10/14

W

For the information of surveyors and the Committee only

Lloyd's Register of Shipping

ENGINE or BOILER VALVES or CONNECTIONS

I have to report that the details as herein described, were submitted

to Messrs. J. H. & Co. Ltd. of 10, Abchurch Lane, London, E.C. 4, who have advised that the same are of the design of Messrs. J. H. & Co. Ltd.

and have been inspected by me as set forth below, and found to be so far as can be seen sound and free from defects.

These have been described as follows:

M. Chamberlain
22-9-06

2 - 1 1/2" dia. Right Angle Valves

220

© 2020



Lloyd's Register Foundation

W