

Proportions

"EMPIRE FAIRY"
"EMPIRE GOBLIN"

Hull Report No. 51664
"Shear" " " 51665

Before these cases receive consideration the Hull Surveyors should be requested to state whether the Combustion Chamber bottom plating is 25/32", also if the Combustion Chamber wrapper plate seams were butt welded. The methods adopted for the heat treatment of the Combustion Chambers after welding might be forwarded for record purposes.

They should also forward the approved Pumping Arrangement plan This will be returned in course of post.

J. H. M.
28.7.42

See Hull 28/7



© 2020

Lloyd's Register
Foundation