

FRAMES, DOUBLE BOTTOM AND
"FRENULINA" - H.KG. 11993.

Cont/.....

AMEND R.B. TO:-

229.5' O.E.

Trunk 120'

^m
INSERT IN R.B.:-

Lengthened and cargo tanks renewed '54. ✓
"pt. Elec.welded".

IT IS FURTHER SUBMITTED the
Surveyors be advised it is concluded
the diameter of chain cable now on
board is as given in the First Entry
and not as reported on the Report 8.

25/6/54
18/6

CBM.
9.6.54.



© 2021

Lloyd's Register
Foundation

008417-008427-0079

thickness of Intercoastal Plate...