

1m.7.38.

Limit to renew the sea inlet valve chest of the refrigerating machinery expired 8,38.

2 E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME "PERLA".

Rpt.

Tri.

No.

12212.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/82.)

Nature of Survey ~~COMPLETION OF~~ SPECIAL SURVEY OF ENGINES AND BOILERS FOR S.S. No. 3

This Survey, <sup>MS</sup> due 1,38 } now held ~~now~~  
<sup>BS</sup> " 6,38 } ~~partly~~  
~~complete~~, and the following repairs carried out (due to wear and tear):-

Crankshaft partly renewed; some bearings remetalled.

Limit:- The valve chest renewed.

It is submitted the vessel is eligible to remain as classed, with notation of \*LMC 9,38 as recommended.  
Without special condition.



© 2021

Lloyd's Register  
 Foundation  
 27.9.38.

008417-008427-0209

and engine examined found in good condition