

Received by Chief Engineer Surveyor .....

Received from Chief Engineer Surveyor .....

SHIP'S NAME

"KARLOVAC"

REPORT

Spt  
Wth

1870  
No. 331

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine Oil Engines 2SCSA with reverse gearing

6 cylinders 240 - 400 mm.

MN 95

~~If Boilers fitted with forced draught~~

Tail Shaft. If fitted with a continuous liner Yes

If fitted with an outside gland of approved type No

The torsional vibration characteristics of the main propelling machinery were approved in the Secretary's letter of 19.8.54. for a service speed of 400 RPM.

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed \*LMC 6,55

In the absence of Certificates it is concluded that the pumps for essential services were made under survey but this should be confirmed.

X 5/8

Yes  
R



29.7.55. 2020

Lloyd's Register  
Foundation