

S.S. "MARIE JEANNE"

This vessel appears to have received some damage through stress of weather, and if it is the Owners' desire that her class should be retained in the Register Book, the repairs to the damage should be carried out under the supervision of the Society's Surveyor.

The Nantes Surveyor
should be advised.

HB

6.11.19.



© 2021

Lloyd's Register
Foundation

008481-008491-0135