

rules

182

Size of manhole in shell

12x16

Size of compensating ring 16x12x1 1/2

plate

85.

ler No. 42833

Made by

Tuston Procter & Co Ltd

Skate Type Trawler N° 99

(John Curran)

Ems.

Report No. 10575

It is submitted that further action in the case is unnecessary until ^{as} this boiler is ~~not intended~~ for a fitted on classed vessel.

Date

19-3-18

Entered in "Unclassed" Boiler Book.

© 2020

Lloyd's Register
Foundation

008507-008514-0020

area of safety valves to superheater

are they fi