

Las.

2m, 2, 15.

19 OCT 1925 4

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME St L K COMMANDANT GAMAS Rpt. Bdx No. 3544

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(“The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.”—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey COMPLETION OF 2nd S.S. No. 1

The 2nd S.S. No. 1 partly held at Bordeaux.

now completed, and the following repairs done (due to wear tear):-
vessel placed in dry dock, bottom cleaned coated, Bulwarks repaired
all Rudder pintles renewed, and minor repairs effected

It is submitted the vessel is worthy to remain as classed, with record of Survey 10-25 Bdx and notation of S.S. Bdx m1-25 as recommended.

100 A.1.

In Self Service

10-25 Bdx.

S.S. Bdx. m1-25

[Signature]
17.10.25



© 2020

Lloyd's Register Foundation

008507. 008514-0028