

"ESSO ORINOCO"

Caracas 35

Before this case receives consideration, it is submitted the Surveyor should be furnished with an extract from the back page of Pir. 6877 on the "EMPORIOS" for his guidance in reporting future donkey boiler surveys, and it should be explained to him in a kindly manner that Rpts. should indicate clearly what has been examined, whether the safety valves have been adjusted, to what pressure they have been adjusted, and whether the oil burning arrangements have been tried in accordance with the Rules. It has already been remarked that this unfortunate Surveyor appears to be in need of guidance in reporting.

*[Signature]*  
8.9.56. ✓

*Return 1 copy of extract*



© 2020

Lloyd's Register  
Foundation

008524-008532-0101