

17 JUN 1960

Ship Surveyor

Received from Chief Ship Surveyor

"NAVEN MONICA"

REPORT Rio.

No. 7548

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/62.)

The class is subject to shell and deck plating etc. in way of No.1 hold being dealt with at next Special Survey.

There is an Appendix Note.

"Surveys Overdue 9,58" is recorded in the Register Book.

The RIO DE JANEIRO Surveyors were advised by cable dated 25.2.60 that provided the ship was fully opened up and examined for Special Survey repairs could be restricted for 18 months or 2 years provided they were satisfied. They were requested to recommend a Modified S.S. Notation with period of validity.

The RIO DE JANEIRO Surveyors report (3,60) this ship placed in dry dock, the requirements of a Modified Special Survey complied with and repairs effected to shell and deck plating etc. including the conditions of class.

IT IS SUBMITTED the ship is eligible to have record of 'DS 2,60' also Notation of SS (M) 3,60 (2 yrs)' assigned, but without special conditions.

DS 2,60
SS(M) 3,60 (2 yrs). Without.

DELETE FROM R.B.
Surveys Overdue 9,58.

IN S.R.L. APPENDIX.
Shell plate A.6 (p.s.f) indented.

ABM
25.5.60



© 2020

Lloyd's Register
Foundation

008533-008540-0137