

The condition of the machinery should be noted at the time of the examination. Where it is considered that re-examination or repairs should be effected before the due date of the next Periodical Examination, a distinguishing mark thus † should be inserted against the item and the circumstances and action recommended described fully under "defects and repairs". Surveys those items which are not applicable to the ship should be cancelled with a black line.

4E

24 NOV 1958

by Chief Engineer Surveyor.....


Received from Chief Engineer Surveyor.....

NAME..... SPRINGBANK..... REPORT..... H.Kg..... No. 14476.

Docking, screwshaft seen.

Some machinery examined and repairs carried out.

IT IS SUBMITTED that this vessel is eligible for the RECORD of TS (CL) 10.58.



© 2020

Lloyd's Register
Foundation

008541-008549-0025

21 CLUTCHES & HYDRAULIC COUPLINGS.....

22 REDUCTION GEARING.....

Shaft be
App
BOARD