

sc.k."GUIMERA"

London 96495a



A limit to repair the boiler expired at the end of 6,31.

In reply to enquiry the Owner writes that he desires to relinquish the classification of the vessel.

IT IS SUBMITTED the vessel's class be withdrawn from the Register Book, and three dots inserted in lieu, indicating withdrawal of class at Owners' request.

Withdraw class.

Insert ...

  
18.7.31.  




© 2020

Lloyd's Register  
Foundation

008541 - 008549 - 00882