

Copy also sent to New York Office

Rpt. C, 11 (Contd.)

Index No.

or London Office use)

# LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

## ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Signal letter HOWT

Ship's Name S/S " NAVIDAD "

Official No.


Port of Registry Panama

This ship has been under survey at La Spezia

on 28th May to 9th July, 1957 and the following alterations to the conditions of assignment of loadlines have now been effected/~~found~~:—

### Particulars of Closing Appliances in Superstructure bulkheads

The two existing openings (1P & 1S) in the after bulkhead of bridge have now been provided with portable steel plates secured by hook bolts; one 4'-0" x 2'-0" opening arranged in each portable plate and closed by W.T. hinged steel door operated from both sides.

  
G. Montani

GMO/np

A copy of this Report has been placed on board.



© 2020

Lloyd's Register  
Foundation

008541 - 008549 - 0123