

by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

NAME JOSIAH MACY REPORT Bdx No. 5491

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

Survey SPECIAL SURVEY OF ~~ENGINES -AND/OR-~~ BOILERS PARTLY HELD ~~FOR S.S.~~ No.

EMC
EMC(M) due 4.48 , partly held 10.47 not advanced.
MS
DBS

~~now further advanced and the following repairs effected (due to..~~

Damage to steering engine electric motor.

Steering engine electric motor armature has been repaired.

It is proposed to complete the survey not stated.

It is submitted that this proposal merits approval and the vessel is eligible to remain as classed, and WILL BE eligible for the record ES 10.47 when the survey has been completed.

The following remains to be done to complete the Survey

The safety valves of the lower donkey boiler to be adjusted.

Yhu



© 2021
1.7.48

Lloyd's Register
Foundation