

Rpt. 8. *Disclassified Section 596*

(Received at London Office)

LA No. 1420

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 19... When held in at Local Office 19... Port of *Callao*

No. in Reg. Book *58612* Survey held at *Tw Sc MV EL Buaro* Date, First Survey *10/53* Last Survey 19...
on the Wood, Iron or Steel *Tw Sc MV EL Buaro*

TONNAGE: Built at *Southampton* By whom *J. L. Thornycroft & Co Ltd* When *1927-5*
GROSS *259* Owners *Anglo-Ecuadorian Oilfields, Ltd* Owners' Address
UNDER DK *190* Managers *Anglo-Ecuadorian Oilfields, Ltd* Port belonging to *Guayaquil*
NET *121*

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage
Cell DBor DBa feet: uE&B feet: f feet: f
total capacity tons: FPT tons: APT tons: MT feet: tons: }
Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.
Last Report, No. *1658* Port *L. C.*

Periodical Surveys, when held, must be reported in detail and verbatim in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form state also the dates and initials of any letters respecting this case.

Manage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Was a damage report made by anyone else? if so, by whom? OIL ENGINES
CONTINUOUS SURVEY.

PAIRS, OR EXAMINATION AS PER RULE FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors.	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed, ...								
Removed and Faird or Repaired								
Faird or Repaired in place								

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M.
Planking of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	(State if on Felt.)
Paintings	Cement or Asphalt	Oil Bunkers	When fitted, Month Year
Stems & Fastenings	Rudder	Scuppers	Boats
Side Plating	Steering gear and its connections	Cargo Hatchways	Masts, Yards, &c.
" " in way of sidelights	Windlass	Hatches	Condition, how ascertained (State if wedges removed.)
Transverse Frames	Have pumps been examined and found efficient?	Planking	Equipment letter
Longitudinals	Have Sluice Valves been examined and found efficient?	Caulking	Anchors, No. of <i>2 + 1-2</i>
Inverses	Have Watertight Doors been examined and found efficient?	Treenails	Cables (State if now ranged)
Stems	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	" length <i>1956</i> mean diamr. <i>1 1/2</i> "
Stems	Air and Sounding Pipes	Transoms, Pointers & Crutches	" Rule length <i>1056</i> size <i>1 1/2</i> "
Bottom Plating	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	Chain Locker
Have the Tanks been examined internally?		" " at other places	Hawsers & Warps
Have the Tanks been tested?		Stringers, Clamps & Shelves	Standing and Running Rigging
		Salting	Sails

General Observations, Opinion as to Class, Recommendation, &c.:
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 23)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 23)	£	:	:	19...
Surveying Expenses (if chargeable)	£	:	:	Received by me,
	£	:	:	19...
Second Surveyor's Fee (if any)	£	:	:	

THURSDAY 25 FEB 1954
Committee's Minute
Character Assigned *9.53 Clb*
S. 9.53 (Clb)
Surveyor to Lloyd's Register of Shipping.
THURSDAY 6 MAY 1954
Lloyd's Register Foundation
008550-008558-0300