

F.E.

Received by Chief Ship Surveyor 75.1.15

Received from Chief Ship Surveyor _____

VESSEL'S NAME

Miss Toronto

Rpt.

Nal.No. 78222

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

35.53

Depth "d"

11.83

Framing: Table No.

Page 9

Description

Single angle as approved

Longitudinal No.

3979

Proportions

Length

8.5

Depth

~~Deck~~ Sheerstrake.50 of an inch instead of .34as required

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to

be classed 100 A.1. (Steel) "Steam Trawler" as recommended.

100 A.1. (Steel) "Steam Trawler"

1 D.WB = DTf 13' 30"BK 8" 4 BH, (Em. Lays a x b)

© 2021
Lloyd's Register
Foundation