

COPY

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.3.

29th September, 1947.

Dear Sirs,

s.s. "EMPIRE SUCCESS."


The Committee have had before them a report of survey carried out by the Society's Surveyors at Halifax, Nova Scotia, (June 1947) from which it noted that the vessel has been surveyed on account of damage alleged to have been caused by a bent LP piston rod and the breakdown of the attached air pump. The LP engine has been examined throughout and the rod renewed and temporary repairs have been effected to the air pump.

It was recommended that the air pump chamber liner be renewed and the junk ring of LP piston examined before the end of the present month, and the class has been continued subject to these items being dealt with accordingly, it being concluded that you have arrangements in hand for this to receive attention.

Yours faithfully,

Clerk to the
Classification Committee.

The Union Castle Mail Steamship Co.,
3, Fenchurch Street,
LONDON E.C.3.



© 2019

Lloyd's Register
Foundation

008608-008617-0184