

MR. POTTS.

"EMPIRE SUCCESS".

See reference in report to omission of deck girder
rider plates and deck doublings at corners of hatchways as fitted
in the ~~bottom~~. *Bochum*

I conclude it requires to be decided whether these
can be dispensed with in this case.

008608-008617-0196

4.6.40.