

m.11.38.

4 E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

Caspine Success

Rpt.

*Hul No. 50675
Mdt 16841*

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/6/92.)

Subject of Survey

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

Survey for Classification.

*Machinery examined throughout
& some repairs effected.*

*The vessel has a L.P. turbine geared to
the thrust shaft (Bauer-Wach). The turbine
shaft is broken & the turbine is out of
action.*

*It is submitted that
this vessel is eligible for*

THE RECORD, AMC 5.40. S 4.40 CL Sp.

*Subject to the bottom man hole flanges being
repaired & the doors refitted & to the Aux. Steam
pipes being tested.*

29/5/40



© 2019

Lloyd's Register
Foundation

008608-008617-0239