

Rpt. S.

(Received at London Office)

No. 91533^aNo. 91533^aDISCLOSED
REPORT of SURVEY for REPAIRS, &c.

Date of writing Report..... 10..... When handed in at Local Office..... 10..... Port of LONDON

No. in Survey held at Date, First Survey Last Survey 10
Reg. Book.

Supp. 60881 on the Wood, Iron or Steel S.K. NORMAN (No. of Vinta)

TONNAGE — Built at North Shields By whom Smiths Dock Co. Ltd. When 1908 12
GROSS 232 Owners L. Haller Owners' Address
UNDER DK. 197 Managers Port belonging to Gochenberg
NET 84Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage
WB=Cell DBorDBa feet; uE&B feet; f feet } Particulars of Classification (which must be inserted
total capacity tons. FPT tons; APT tons; MT feet tons. } precisely as in Register Book & Supplements).N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 89891 Port Lw

CHARACTER
* for Special Survey.
Date of last Survey and of
Periodical Survey.
100 AI,
Str. Fowler,
326.
S.S. FLT. No 3—1-20.
S.S. FLT. No. 1-24.
LMC,
326.
T.S. 326C

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Society's Freeboard (if assigned) as painted on Ship and now verified

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faird or Repaired								
Faird or Repaired in place								

PRESENT CONDITION OF THE

cks	State if Tanks have been examined inside	Dblng. Plates under Sounding Pipes	Copper, or T.M. of Wood Vessels
plking of Decks	State if Tanks now tested	Engine Room Skylights	(State if on Feet). When put on, Month
amings	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	Boats
ams & Fastenings	Ceiling	Scuppers	Masts, Yards, &c.
tside Plating	Cement or Asphalt	Cargo Hatchways	Condition, how ascertained
easthooks	(State which.) Rudder	Hatches	(State if wedges removed)
ansoms	Steering gear and its connections	Planking	Sails
ames	Windlass	of Wood Vessels	Equipment letter
verse Frames	Have Pumps now been examined and found effi- cient?	Caulking	anchors, No. of
agitudinals	Have Sluice Valves now been examined and found efficient?	ditto	Cables (State if now ranged)
nsverses	Have Watertight Doors now been examined and found efficient?	Treemails	length
ors	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	(on board) size
isons		Transoms, Pointers, & Crutches ditto	Rule length
ingers		Timbers of Frame at openings ditto	Hawser & Warps
er Bottom Plating		Ditto ditto at other places ditto	Standing and Running Rigging
		Stringers, Clamps & Shelves	
		Salting	
		(State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:—

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—“to remain as now classed in the Register Book without fresh record of Survey,” “to remain as classed and to have record of survey 1,24,” or “to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND24, &c.”

ey Fee (per Section 20)	£	:	:	Fees applied for,
ial Damage or Repair Fee (if any)	£	:	:	19
(per Sec. 20)				Received by me,
elling Expenses (if chargeable)	£	:	:	19
nd Surveyor's Fee (if any)	£	:	:	

TUES. 28 JUN 1907

Committee's Minute

Character Assigned

with class + insert (. . .)

Surveyor to Lloyd's Register of Shipping.

General Committee
Thursday 30th June 1907
Classing Committee
decision confirmed

Is Certificate required? If so, to be sent to

008608-008617-0319

[illegible]

ANCHORS.

Of Stockless, State Mechanical Tests

CHAIN CABLES.

Iron Stream Chain }
or Steel Wire.... }