

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME *Mt S. K. The Norman* Report *Lv* No. *89881*For the CHIEF SHIP SURVEYOR ~~and~~ CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Cladding Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Cladding Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

When due

Subt
Damaged stem to be repaired at owners
convenience: Engine Room casing & RQD
planking to be repaired at or before
next S.S.



© 2019

Lloyd's Register
Foundation

008608-008617-0320