

F.E.

Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

NAME Steel S.S. "KIFUKU MARU". Rpt. Kob. No. 2367

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 79

Depth "d" 16.0

Drawing: Table No. 3 page 14.

Description Bulb angle as approved.

Longitudinal No. 30415

Proportions $\frac{\text{Length}}{\text{Depth}} = 10.7$

g. k Sheerstrake as approved.

This vessel appears to have been built in accordance with the rules and the approved plans, and it is submitted she is eligible to be classed \times 100 A.L. (Steel) Awning Dk. with freeboard," as recommended. The Summer freeboard of $9.3\frac{1}{2}$ from centre of disc top of statutory deck line at Awning deck, now marked on the vessel's sides, to be inserted in the classification certificate, and entered in the Register Book, and further, the remaining freeboards, shown on the accompanying verification form to be inserted in the certificate of classification.

2 Dks. (Steel) and Awning Dk. (Steel).

Cell DB 334' 1118t. FPT 126t. APT 93t.

FK. Collision BH to Awning Dk. 5 BH to upper Dk. Cem. A. & C.P.

The Surveyors should be informed it is concluded the class P.T.O.

008618-008622-0051

6.2.19.

Lloyd's Register Foundation

of this vessel should be Awning Dk. as in the sister vessels
not Shelter Dk. *that cargo hatches are fitted in the tween decks.*

First Entry reports of a later date should be sent to
Surveyors.

Mr Cook

M



© 2021

Lloyd's Register
Foundation