

COPY

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.3.

20th August, 1947.

Dear Sirs,

I am asked to confirm the discussions which took place at Grimsby last week between your Superintendent, Mr. Gidley, and Mr. McMillan, the Society's Principal Surveyor at Hull, and Mr. Piddington the local Ship Surveyor, regarding a defective sheerstrake plate in your trawler "BELLONA".

The Grimsby Surveyors in June last reported that the sheerstrake plate abreast the wheelhouse on the port side was wasted and holed in way of a deck scupper and recommended its renewal.

It is understood from Mr. McMillan that the necessity for this repair is not questioned by your Superintendent, and the Committee consider it should receive attention at the earliest possible moment.

Moreover, it is now more than eleven years since the vessel was last submitted to Special Survey and the Committee must ask for definite arrangements to be made for one to be held at an early date if the vessel is to retain her class.

I shall be glad if you will give these matters early consideration and let me know what arrangements you are making in compliance.

Yours faithfully,

Copy sent Gms & Hul

Clerk to the
Classification Committee

Messrs. Consolidated Fisheries Ltd.
Auckland Road,
Fish Docks,
Grimsby.



© 2021

Lloyd's Register
Foundation

008618 + 008627 + 0069