

COPY.

Food Fishing Vessel "ALEKSY" Annual Classification Survey due 9,49.
Intermediate Machinery Survey due 9,49.
Screwshaft Survey due 9,50.

" " "HILARY" Annual Classification Survey due 3,48.

" " "JANUARY" Annual Classification Survey due 7,48.
Intermediate Machinery Survey due 7,49.
Screwshaft Survey due 7,50.

" " "KSAWERY" Annual Classification Survey due 4,49.
Intermediate Machinery Survey due 4,50.

" " "WALERY" Intermediate Machinery Survey due 5,49.
Screwshaft Survey due 5,50.

Steam Trawler "MERKURY" Special survey due 4,50.
Boiler Survey due 7,50 (partly held 4,50). To
complete for the record B.S. 4,50 the safety
valves remain to be adjusted.

S.S. "NAROCZ" Boiler survey due 1,50 (partly held 3,50). To
complete for the record B.S. 3,50 the star-
board boiler remains to be examined throughout

Food Fishing Vessel "NEPTUNIA" The forecastle side planking (stbd. side)
requires to be specially examined and dealt
with as necessary by 12,50.

S.S. "PETR. WELIKY" The port main engine M.P. column and the aft
fan engine bedplate and entablature required
to be examined by 5,50.
Boiler Survey due 11,50.

S.S. "PILOF 50" The main engine fuel pump required to be
examined under working conditions after repair

Steam Trawler "POKUCIE" Special Survey due 8,50 (partly held on
machinery 4,50 by the examination of all main
engine valves and casings, crank and thrust
shafts and bearings.
Boiler Survey due 7,50.

" " "POLESIE" Special Survey due 5,50 (partly held on
machinery 3,50 by the examination of the main
engine in its entirety and the thrust shaft
and bearings.
Screwshaft Survey due 4,50.

S.S. "WEGA" Permanent repairs were required to main engine
seating by 7,50.
Boiler Survey due 6,50 (partly held 2,50 by
the examination of the safety valves and other
mountings.

Steam Trawler "WULKAN" Indented No.1 sheerstrake plate (stbd. side
fwd.) requires to be specially examined and
dealt with as necessary by 12,50.



© 2021

Lloyd's Register
Foundation

008617-008627-0139.1