

22 MAY 1942

2m,3,42.

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "EVELINE NUTTEN" REPORT Abn. No. 20773

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

(The 2nd S.S. No.3 due 5,40).

A notation of 'Examined 6,41' (12 months) has been assigned.

The class is subject to the stem being repaired at the Owners' convenience.

The rudder mainpiece E.W. 6,41 requires to be specially examined at the next dry docking.

The ABERDEEN Surveyors now report the vessel placed on a pontoon, bottom coated, a General Examination made and minor repairs carried out.

The rudder mainpiece, as above, examined and found efficient.

It is submitted the vessel appears worthy to remain as classed with record of docking survey 5,42 subject to the stem and rudder mainpiece being dealt with as indicated above, and that a notation of 'Examined 5,42' valid for 12 months, as recommended, be assigned.

As now, )  
5,42 Abn. ) Subject etc.

'Examined 5,42'



2021  
20.5.42

Lloyd's Register  
Foundation