

2 E

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

"AFRICAN QUEEN"

REPORT

Nwc.

No. 109981.

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/42.)

Survey COMPLETION OF SPECIAL SURVEY OF ENGINES-AND BOILERS

This Survey, due 11,51 ^{now} ~~partly~~ held ^{now} completed, and the following repairs carried out (due to -----)

Docking. Both screwshafts drawn and examined and skimmed in lathe.

It is submitted the vessel is eligible to remain as classed, with notation of DBS 11,52, Both S 8,52 as recommended.



© 2020

Lloyd's Register Foundation

10. 12. 52.

008628-008633-0082