



RECEIVED
25 MAR 1950

Lloyd's Register of Shipping,

Westminster Buildings,
Theatre Square,

Nottingham, 24th March, 1950.

AN8D.....

Sir,


re return Nottm. Report No. 748, duly signed. The omission of your signature is regretted.

Our request that the Generator Makers Test Certificate be included in future is noted, but at the same time we would point out, in the case of Ruston & Hornsby oil engine generating sets 100 KW, the temperature test at full load is invariably omitted during the combined running test, and the temperatures, shown in the engine test sheets, in addition to the generator Test Sheets.

Engine Test Sheets were forwarded with our report No. 748, in the first instance.

Yours faithfully,
The Surveyors

per:-



© 2020

Lloyd's Register
Foundation

Secretary,

008628-008633-0096

Damage or Repair Fee (if any) Repairs
(per Sec. Alterations & O F

157: 10: -

15 NOV 1950

Referred to the D.O.

R.H.P.

For Engineer Surveyors (F.E. Rpts.) to note.

N Mea.

J.S. 27-3-50.



© 2020

Lloyd's Register
Foundation

Special Day
(per

NOT

Appe
mech
fo b