


No 48



For the information of Surveyors and the Committee only. NOV 1950

Received at \_\_\_\_\_ Office, \_\_\_\_\_ 19\_\_\_\_

# Lloyd's Register of Shipping.

(Report on Machinery, No. 24353 Port GRIMSBY.)

## ENGINE or BOILER VALVES or CONNECTIONS.

I have to report that the Details, as herein described, manufactured  
W. Miller of Glasgow  
AFRICAN QUEEN (a BADGER) being repaired  
Engines or Boilers No. \_\_\_\_\_ constructed by J. S. DOUG.  
\_\_\_\_\_ of Grimby

Inspected by me as set forth below, and found to be, so far as can  
be ascertained, sound and free from defects.


When despatched to Grimby

By S. H. Macdonell

Glasgow 18.5.50

NOTE W.P. stated under 200 lbs.

						T.P.
4 - 2 1/2" Bore x 10 W.G. S.D. 4 tappets	Uain	Stm	pipe	Nº 1 (Sh Nº 135)		500 lbs.
2 - 1 1/2" " x 12 " " " "	feed	pipes	Nº 2 (Sh Nº 164)			625 lbs.
1 - 1 1/2" " x 6 " " S.D. Steel	"	"	Nº 2 (Sh Nº 165)			625 lbs.
1 - 1" " x 12 " " S.D. 4 tappets	"	"	Nº 2 (" " 167)			"
1 - 1" " x 12 " " " "	"	"	Nº 2 (" " 168)			"
1 - 1" " x 8 " " S.D. Steel	"	"	Nº 3 (" " 170)			"
1 - 1" " x 8 " " " "	"	"	Nº 1 (" " 171)			"
1 - 1" " x 8 " " " "	"	"	Nº 1 (" " 173)			"
4 - 1" " x 8 " " " "	"	"	Nº 1 (" " 172)			"
1 - 1" Bore fab. Steel Turbine feed						625 lbs.
2 - 1" G.M. Globe Valves feed						625 lbs.
12 & 18.5.50						



Lloyd's Register  
Foundation

008628-008633-0115