

The condition of any of the following items is to be described as "good" only when the part has been examined, found or placed in good condition, and is ~~the due date of the next Periodical Examination. Where it is considered that re-examination or repairs should be effected before the due date of the next examination mark thus + should be inserted against the item and~~ distinguished mark thus + should be inserted against the item and

Class is subject to Ballast Pump water end casting being renewed before the completion of the present Special Survey and to the donkey boiler shell plate repairs being further examined by 10.57. also to Windlass first Reduction Pinion being renewed at earliest opportunity 3 E

29 JUL 1957

Received from Chief Engineer Surveyor

Chief Engineer Surveyor

NAME "PACIFIC PEARL"

REPORT VKA

No. 2298.

C.S. due 6.56 partly held as C.S. now further advanced.

and the following repairs effected (due to Wear & Tear).

Some parts of Main Engine & attached Pumps examined.

It is proposed to complete the Survey

It is submitted that this proposal merits approval and the vessel is eligible to remain as classed, and WILL BE eligible for the record

C.S. with date

when the Survey has been completed.  
Subject to Ballast Pump water end casting being renewed at end of present voyage in July 1957  
and as above regarding donkey boiler & Windlass Pinion.

The following remains to be done to complete the Survey.

See Form 7E.



© 2020

Lloyd's Register  
Foundation

008628 - 008633 - 0247

Date of Committee

10 AUG 1957

28

1. Aug 1957