

COPY

NO. 7444

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

Port WELLINGTON, N.Z.

18th April, 1957.



This is to Certify that I have

Surveyed the ^{Donkey}Boiler and ^{Part}Machinery of the M.V. "PACIFIC PEARL"

(ex Holmdale) 679 gross tons of Panama on the 1st March, 1957 and subsequently as the vessel lay afloat and on the floating drydock at this port on account of Damage to the M.E. driven circulating water pump, Docking Survey, Advancement of Continuous Survey of Machinery, Donkey Boiler Survey and Repairs, and that I have transmitted to the Committee of Lloyd's

Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction, and that I have Recommended that the record of D.B.S. 4,57 now and C.S. (with date),

be made in the Register Book in the case of this vessel when

the survey has been completed. subject to the welded repair to the donkey boiler shell plate being further examined by October, 1957 (6 months limit), to the windlass first reduction pinion being renewed at the earliest opportunity and to the Ballast Pump water end casting being renewed before completion S.S.

PARTS NOW EXAMINED :- Propeller, Sea Connections, Fastenings, Main Engine:- All Cylinders, Covers, Pistons, Valves and Gears, Connecting Rods. Top Ends and Edge Pins, Crankpins and bearings and Nos. 2, 3, 4, 5, 6 and 7 Journals and Bearings, Thrust Block, shaft and Bearings. Intermediate shaft and bearing. M.E. Driven Circulating Water Pump. Crankcase Doors. Main L.O. Cooler Aux. Engine Driven Compressor, Windlass, Fire Extinguishing Arrangements. Steam Generator Engine (Starboard side). Diesel Generator Engine (Port side). Auxiliary Electrical Equipment. Donkey Boiler in its entirety. Oil Fuel Suction lines, Fittings and Controls. General Service Pump.


Robbintsen for F.E. Turpie & self.
(L.O. CHRISTENSEN and (F.E. TURPIE)

P.T.O.

Engineer Surveyor to Lloyd's Register.

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :-
The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed.
It is understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member Surveyors, or other Officers or Agents of the Society."

30m.12.51. (MADE AND PRINTED IN ENGLAND.)

Lloyd's Register
Foundation

008628-008633-0260

