

5 E

Engineer Surveyor

Received from Chief Engineer Surveyor

AME 'HOLMDALE'

REPORT

Ddn.

No. 3160

the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points noted in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


~~DAMAGE & WEAR AND TEAR.~~

IMC due 11.53 partly held as a CS now complete.  
DBS due 11.52 now held.

Minor repairs due to wear and tear.

ing.

It is submitted the vessel is eligible to remain as classed, with record of Survey IMC CS 6.52. as recommended DBS 6.52.



© 2020

Lloyd's Register  
Foundation

008628-008633-0278

4. 9. 52.

Two-S