

21 MAY 1942

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "TJISAROE"..... REPORT Sba..... No..... 4518.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The 2nd S.S. No.1. became due 10,41.

(The class is subject to 15 fathoms of chain cable being supplied).

The SOURABAYA Surveyor reports (12,41) the vessel placed in dry dock, bottom coated and a GENERAL EXAMINATION held, and no immediate repairs found necessary.

15 fathoms of chain cable have been supplied.

It is submitted the vessel appears worthy to remain as classed and to have record of docking survey 12,41 without special condition and that a notation of 'Examined 12,41' considered valid for 12 months, be assigned.

As now,)
12,41 Sba.) Without etc.



© 2021
18.5.42

Lloyd's Register
Foundation

008634-008640-0002