

008641-008647-0074

13 AUG 1920

Chief Surveyors 12.8.20.

Received from Chief Surveyors

SHIP'S NAME *St. or. Tocantins* Report *NRK* No. *18113*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/22.)


2nd No. *1* SURVEY PARTLY HELD. *repairs.**6.19.*

When proposed to be completed

*Machinery survey held 13.1.20*

of Survey held, &amp;c.,

The Owners should be asked to state what definite arrangements they propose making for the Special Survey to be completed & the temporary repairs to crank shaft examined

*i Rev. 16/8/20*

© 2021

Lloyd's Register  
Foundation