

clearly indicated. Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey

100 A1 with freshboard

TMC 8

26 JUN 1957

M 2/5
CL 1
8/52

Received from Chief Ship Surveyor

NAME "IOANNIS INGLESSIS" REPORT Gen. No. 22350

Existing Conditions of Class: Subject to No.1 plate (p.s.f.) in 4th strake below sheer being renewed and to No.6 plate in 2nd below sheer etc. (s.s. from aft) being dealt with by completion of S.S., to a bower anchor and 45 fms. of chain cable being supplied at the earliest opportunity, and to starboard settling tank bulkhead plating (leakage) being permanently repaired by 4,57.

Advancement of Class (B) (As before ~~xxxxxxx~~) ACTION is DEFERRED for completion of S.S.

Special Survey (C) due 8,56 - commenced Rot. 1,56 and subsequently advanced.

Advancement of Present Survey: (Afloat ~~xxxxxxxxxxxx~~)

Advancement of Special Survey: Alterations in accordance with approved plans: Damage repairs (various causes) and to part of the deferred items as above: Equipment (a bower anchor and 45 fms.c.c. supplied - bower anchor not verified with test certificate).

Special Features:

Permit Certificate in order (Yes-No-None)

Outstanding: (If any for S.S.) ~~xxxxxxxxxx~~

TO COMPLETE THE S.S.:- See this report.

to be completed by:

Recommendation:


SUBMITTED ACTION and NOTATION of +SS Tri. 8,56' be DEFERRED for completion of the Special Survey, subject to bower anchor (supplied Gen. 4,57) being verified with test certificate at the earliest opportunity and to No.1 plate in 4th below sheer (p.s.f) being renewed by completion of the Special Survey but without other conditions.

As Now. Subject Without.

DELETE 'ENDORSEMENT OF CERTIFICATE'

Freeboard Surveyors to note. MR 27.6.57

© 2021 1146-57



Lloyd's Register Foundation

Blk(new)

008648-008655-0033